



Mattel, Inc  
333 Continental Blvd. El Segundo, California 90245 USA  
(310) 252-2000

---

**Certificate of Conformance**

---

**SKN/SKU No.:** GFC88  
**Associated Asst. Numbers:** GVK15,GFC85  
**Product Name:** POK CHARMANDER  
**Certificate Number:** COC\_GFC88\_March 03, 2020+00000005451662

**Date Created:** 12/16/2020

The product(s) listed above are hereby certified by the Importer listed below to meet the applicable U.S. Consumer Product Safety Commission standards:

**Consumer Product Safety Improvement Act (including phthalates and ASTM F963 provisions)**  
**Consumer Product Safety Act (including 16 CFR Part 1303)**  
**Federal Hazardous Substances Act**

**Manufacturer:** Mattel, Inc

**U.S. Importer/Certifier:** MATTEL, INC., 333 CONTINENTAL BOULEVARD , , California 90245, United States

**Private Labeler:** Internal

---

These products were manufactured on February 2020 - February 2021 in: Shenzhen, China

Testing of representative samples was conducted by:

Mattel Toys Technical Consultancy (SZ) Ltd. – Quality Lab, 6/F., Building 6, Hangsangchong Industrial Center, No. 107, Fukang Road, Henggang, Longgang District, Shenzhen, Guangdong, China, Ph. +86 755 2886 3811  
Testing was conducted on: March 03, 2020 / Test Report Document ID: 3877439

Mattel Toys Technical Consultancy (SZ) Ltd. – Quality Lab, 6/F., Building 6, Hangsangchong Industrial Center, No. 107, Fukang Road, Henggang, Longgang District, Shenzhen, Guangdong, China, Ph. +86 755 2886 3811  
Testing was conducted on: March 03, 2020 / Test Report Document ID: 3877435

Mattel Toys Technical Consultancy (SZ) Ltd. – Quality Lab, 6/F., Building 6, Hangsangchong Industrial Center, No. 107, Fukang Road, Henggang, Longgang District, Shenzhen, Guangdong, China, Ph. +86 755 2886 3811  
Testing was conducted on: March 03, 2020 / Test Report Document ID: 3877449